

PUBLIC UTILITIES COMMISSION

505 VAN NESS AVENUE  
SAN FRANCISCO, CA 94102-3298



October 18, 2006

Hal Snyder, Vice President  
Local Distribution Services  
Southern California Gas Company  
P.O. Box 3249, Terminal Annex  
Los Angeles, CA 90051

**SUBJECT:** Notice of General Order (G.O.) 112-E Compliance Inspection of Southern California Gas Company, Gas Storage facilities.


Dear Mr. Snyder:

On behalf of the Utilities Safety and Reliability Branch of the California Public Utilities Commission, I conducted a G.O. 112-E audit of Aliso Canyon, Honor Rancho, Goleta, and Playa del Rey Districts of your Gas Storage facilities on September 26-29, 2006. The audit included review of records from August 2005 to September 2006, and field inspections of your natural gas facilities.

I did not observe any violations of G.O. 112-E, Reference Title 49, Code of Federal Regulations, Parts 191 and 192.

If you have any questions, please call me at (213) 576-7014.

Sincerely,



Matthewson Epluna  
Utilities Safety and Reliability Branch  
Consumer Protection and Safety Division

cc: Steve Intably, CPUC-LA

## Storage - Aliso Canyon

### DATA SHEET CPUC COMPLIANCE INSPECTION - G.O. 112-E

FOR THE PAST YEAR OF 2004

- |    |                                      |      |
|----|--------------------------------------|------|
| 1. | Map of Area                          | YES  |
| 2. | Organization Charts                  | YES  |
| 3. | Welder/Joiner Qualification Listings | NONE |
| 4. | Pipe Statistics,                     |      |

Pipeline Data (20% SMYS)

Total Miles	<u>54</u>		
Coated	<u>54</u>	Protected	<u>0</u>
Bare	<u>0</u>	Protected	<u>0</u>

Pipeline Data (less than 20% SMYS)

Total Miles	<u>0</u>		
Coated	<u>0</u>	Protected	<u>0</u>
Bare	<u>0</u>	Protected	<u>0</u>

Pipeline Data (20% SMYS)	<u>54</u>
Pipeline Data (less than 20% SMYS)	<u>0</u>

5. Cathodic Protection

Number of Rectifiers	<u>4</u>
Number of Interference Bonds 2 mo	<u>0</u>
Number of Interference Bonds 12 mo	<u>0</u>
Number of C.P. Areas	<u>30</u>
Number of C.P. Test Points (annual reads)	<u>142</u>
Number of C.P. 10% Reads (year end)	<u>0</u>

6. Class Location Changes

Number of Changes	<u>0</u>
-------------------	----------

7. Emergency Plans

Number of Emergency Manuals	<u>1</u>
-----------------------------	----------

Number of Leak Indicators 11  
 Emergency Exercise Past Year YES

NO X

8. Gas Odorant Testing

Number of Testing Locations 3

9. Number of Persons Qualified for Hot Taps 0

10. Leak Statistics, Past Four Years

	Total Number of Leak Repairs			
	2002	2003	2004	2005
Code I	0	0	1*	
Code II	0	0	0	0
Code III	0	0	0	0
Number of Corrosion Leak Repairs				
	0	0	0	0

\* was classified as a mechanical failure, flange gasket leak.

11. Pressure Regulation Stations, Relief Valves, Gauges

Number of Regulator Stations 0

Number of Relief Valves 469

Number of Gauges  
 Recording 0  
 Telemeter 1

12. Critical Valves

Number of Critical Valves 140

13. Vaults

Number of Vaults 200 cu. Ft. and Over 2